

CONSTRUCTION UPDATE

February 15, 2022

UPCOMING CONSTRUCTION ACTIVITIES

El Camino Real (ECR) Lane Closures

ECR work continues intermittently according to this approximate construction schedule:

Roadway Repaving: April—May 2022

Other Offsite Impacts

· Sidewalk and street improvement work continues.

Office Buildings

Building 1

- Elevator 1 is complete. State certification will follow.
- · Exterior painting has begun.
- · Waterproofing of the balconies has begun.
- · Roof tile and membrane installations continue.
- Interior modifications and elevators 2 and 3 installation continues.
- Interior wall metal stud framing is complete. Installation of drywall and insulation will follow, pending inspections.

Building 2

- · Landscape planting and balcony planters has begun.
- Installation of the wood trellis beams at the balcony has begun.
- In the basement, fence and bicycle locker installation has begun.
- Concrete pours for planter boxes, sidewalks, curbs and gutters are ongoing.
- Driveway paver installation continues.

Building 3

- Emergency generator infrastructure and concrete pad construction at the south side has begun.
- · Concrete pours for sidewalks, curbs and gutters are ongoing.
- · Driveway paver installation continues.

CONTACT INFORMATION

Construction Information Line (650) 497-4052

Email

middleplaza@stanford.edu

Website

middleplaza.stanford.edu

On-site Construction Manager Nic Durham ndurham@stanford.edu (650) 725-2960

City of Menlo Park (650) 330-6704

After Hours/Emergency 911



Insulating Co-Working Space in Building A

Thanks for your patience during construction



CONSTRUCTION UPDATE

February 15, 2022

UPCOMING CONSTRUCTION ACTIVITIES (continued)

Residential Buildings & Surrounding Areas

- Construction of courtyard planters on south side has completed; work continues on north side.
- Exterior scaffolding is expected to be taken down by end of February.
- Final mechanical, electrical and plumbing inspections for yoga studios are in progress.
- Construction of co-working spaces, community rooms, lounge, and lobby continues.
- Exterior sheathing, roofing, detailing, and inspections continue.
- Siding, weatherproofing, and exterior painting continues for Buildings A and B.
- Interior construction and inspections for Building A, B and C continue.
- Electrical installations continue.
- Balcony railing work continues.
- · Pool equipment installation continues.

Garage

- HVAC and electrical inspections continue.
- Meter installation is expected to complete by early March.
- · Seismic bracing continues.
- · Insulation and steel installation are ongoing.

Stormwater Drainage System

- Water tie-in is nearing completion, pending inspections.
- Bioswale and onsite landscaping will follow.



Middle Plaza Site Plan

CONTACT INFORMATION