

CONSTRUCTION UPDATE

February 22, 2022

UPCOMING CONSTRUCTION ACTIVITIES

El Camino Real (ECR) Lane Closures

ECR work continues intermittently according to this approximate construction schedule:

• Median Work: March–May 2022

Roadway Repaving: April–May 2022

Other Offsite Impacts

Sidewalk and street improvement work continues.

Office Buildings

Building 1

- · Installation of drywall and insulation has begun.
- · State certification of elevator 1 is in progress.
- Interior modifications and installation of elevators 2 and 3 continues.
- Exterior painting continues.
- · Waterproofing of the balconies continues.
- Roof tile and membrane installations continue.

Building 2

- Landscape planting and balcony planters continues.
- Installation of the wood trellis beams at the balcony continues.
- In the basement, fence and bicycle locker installation continues.
- · Driveway paver installation continues.
- Concrete pours for planter boxes, sidewalks, curbs and gutters are ongoing.

Building 3

- Emergency generator infrastructure and concrete pad construction at the south side continues.
- · Concrete pours for sidewalks, curbs and gutters are ongoing.
- · Driveway paver installation continues.

CONTACT INFORMATION

Construction Information Line (650) 497-4052

Email

middleplaza@stanford.edu

Website

middleplaza.stanford.edu

On-site Construction Manager Nic Durham ndurham@stanford.edu (650) 725-2960

City of Menlo Park (650) 330-6704

After Hours/Emergency 911



Courtyard Planters Nearing Completion

Thanks for your patience during construction



CONSTRUCTION UPDATE

February 22, 2022

UPCOMING CONSTRUCTION ACTIVITIES (continued)

Residential Buildings & Surrounding Areas

- Exterior scaffolding is expected to be taken down by end of February.
- Final mechanical, electrical and plumbing inspections for yoga studios are in progress.
- Construction of co-working spaces, community rooms, lounge, and lobby continues.
- Exterior sheathing, roofing, detailing, and inspections continue.
- Siding, weatherproofing, and exterior painting continues for Buildings A and B.
- · Construction of courtyard planters on north side continues.
- Interior construction and inspections for Building A, B and C continue.
- · Electrical installations continue.
- Balcony railing work continues.
- · Pool equipment installation continues.

Garage

- HVAC and electrical inspections are nearing completion.
- Meter installation is expected to complete by early March.
- · Seismic bracing continues.
- Insulation and steel installation are ongoing.

Stormwater Drainage System

- Water tie-in is nearing completion, pending inspections.
- Bioswale and onsite landscaping will follow.



Middle Plaza Site Plan

CONTACT INFORMATION