

# **CONSTRUCTION UPDATE**

March 1, 2022

# **UPCOMING CONSTRUCTION ACTIVITIES**

# El Camino Real (ECR) Lane Closures

ECR work continues intermittently according to this approximate construction schedule:

• Median Work: March–May 2022

Roadway Repaving: April–May 2022

# **Other Offsite Impacts**

Sidewalk and street improvement work continues.

# **Office Buildings**

# **Building 1**

- · Installation of drywall and insulation continues.
- Interior modifications and installation of elevators 2 and 3 continues.
- · Exterior painting continues.
- · Waterproofing of the balconies continues.
- · Roof tile and membrane installations continue.

#### **Building 2**

- · Landscape planting and balcony planters continues.
- Installation of the wood trellis beams at the balcony continues.
- In the basement, fence and bicycle locker installation continues.
- · Driveway paver installation continues.
- Concrete pours for planter boxes, sidewalks, curbs and gutters are ongoing.

## **Building 3**

- Emergency generator infrastructure and concrete pad construction at the south side continues.
- Concrete pours for sidewalks, curbs and gutters are ongoing.
- Driveway paver installation continues.

#### CONTACT INFORMATION

**Construction Information Line** (650) 497-4052

#### **Email**

middleplaza@stanford.edu

#### Website

middleplaza.stanford.edu

On-site Construction Manager Nic Durham ndurham@stanford.edu (650) 725-2960

City of Menlo Park (650) 330-6704

After Hours/Emergency 911



North Side Courtyard Planters In Progress

Thanks for your patience during construction



# **CONSTRUCTION UPDATE**

March 1, 2022

# **UPCOMING CONSTRUCTION ACTIVITIES (continued)**

# **Residential Buildings & Surrounding Areas**

- Exterior scaffolding is expected to be taken down by early March.
- Final mechanical, electrical and plumbing inspections for yoga studios are in progress.
- · Construction of co-working spaces, community rooms, lounge, and lobby continues.
- Exterior sheathing, roofing, detailing, and inspections continue.
- Siding, weatherproofing, and exterior painting continues for Buildings A and B.
- · Construction of courtyard planters on north side continues.
- Interior construction and inspections for Building A, B and C continue.
- Electrical installations continue.
- Balcony railing work continues.
- · Pool equipment installation continues.

## Garage

- HVAC and electrical inspections are nearing completion.
- Meter installation is expected to complete by early March.
- · Seismic bracing continues.
- Insulation and steel installation are ongoing.

## **Stormwater Drainage System**

- Water tie-in is nearing completion, pending inspections.
- Bioswale and onsite landscaping will follow.



Middle Plaza Site Plan

## **CONTACT INFORMATION**