

# **CONSTRUCTION UPDATE**

March 15, 2022

# **UPCOMING CONSTRUCTION ACTIVITIES**

# El Camino Real (ECR) Lane Closures

 ECR work continues intermittently according to this approximate construction schedule:

Median Work: March–April 2022Sidewalk Work: May–July 2022

Roadway Repaving: July–August 2022

# **Other Offsite Impacts**

· Sidewalk and street improvement work continues.

# **Office Buildings**

# **Building 1**

- Installation of drywall and insulation continues.
- Interior modifications and installation of elevators 2 and 3 continues.
- Exterior painting is complete.
- Roof tile and membrane installations continue.

## **Building 2**

- Landscape planting and balcony planters continues.
- Installation of the wood trellis beams at the balcony continues.
- Driveway paver installation continues.
- Concrete pours for sidewalks, curbs and gutters are ongoing.

## **Building 3**

- Emergency generator infrastructure and concrete pad construction at the south side continues.
- Concrete pours for sidewalks, curbs and gutters are ongoing.
- Driveway paver installation continues.

#### **CONTACT INFORMATION**

**Construction Information Line** (650) 497-4052

#### **Email**

middleplaza@stanford.edu

#### Website

middleplaza.stanford.edu

On-site Construction Manager Nic Durham ndurham@stanford.edu (650) 725-2960

**City of Menlo Park** (650) 330-6704

After Hours/Emergency 911



Paving of Garage Entrance

Thanks for your patience during construction



# **CONSTRUCTION UPDATE**

March 15, 2022

# **UPCOMING CONSTRUCTION ACTIVITIES (continued)**

# **Residential Buildings & Surrounding Areas**

- Exterior scaffolding is expected to be taken down by March 17.
- Final mechanical, electrical and plumbing inspections for yoga studios are in progress.
- Construction of co-working spaces, community rooms, lounge, and lobby continues.
- Exterior sheathing, roofing, detailing, and inspections continue.
- Siding, weatherproofing, and exterior painting continues for Buildings A and B.
- Construction of courtyard planters on north side is nearing completion.
- Interior construction and inspections for Building A, B and C continue.
- · Electrical installations continue.
- · Balcony railing work continues.
- · Pool equipment installation continues.
- Pool deck paver installation in progress.

## Garage

- HVAC and electrical inspections are nearing completion.
- · Meter installation is complete.
- Seismic bracing continues.
- · Insulation and steel installation are ongoing.

# **Stormwater Drainage System**

- Water tie-in is undergoing inspections.
- Bioswale and onsite landscaping will follow.



Middle Plaza Site Plan

## **CONTACT INFORMATION**